

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error or Definition	Errors	Ref #
28	BRS	11	(US-20040183013-\$).did. or (US-4551599-\$ or US-5001349-\$ or US-5557105-\$ or US-6038018-\$ or US-6084238-\$ or US-6190579-\$ or US-6366342-\$ or US-6400090-\$ or US-6563321-\$ or US-6593152-\$).did.	US-PGPUB; USPAT	2005/03/25 14:41				S55
29	BRS	3	S55 and leak\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/25 14:56				S56
30	BRS	8	250/310 and stage near5 leak\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/25 15:00				S57
31	BRS	0	250/310 and stage near5 gas near5 leak\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/25 15:00				S58
32	BRS	395	stage near5 gas near5 leak\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/25 15:01				S59
33	BRS	23	S61 and electron adj beam	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/28 07:00				S62

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Error	Ref #
34	BRS	0	S62 and stage near5 partition	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/28 07:01				S63
35	BRS	6	S62 and stage near5 plate	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/28 07:01				S64
36	BRS	15	S65 and pump\$4 near5 groov\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/28 08:02				S66
37	BRS	396	stage near5 gas near5 leak\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/28 08:05				S65
38	BRS	2	electron adj beam and wafer near5 gas adj leak\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/28 08:08				S67
39	BRS	226	beam near5 chamber and gas adj leak\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/28 08:08				S68

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Ref #
40	BRS	2	"4191385".pn.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/28 08:32			S70
41	BRS	8	("3201188" "3520055" "3691720" "3704504" "4141456" "4142004").PN.	US-PGPUB; USPAT; USOCR	2005/03/28 08:33			S71
42	BRS	39	("4191385").URPN.	USPAT	2005/03/28 08:35			S72
43	BRS	0	("6816238").URPN.	USPAT	2005/03/28 08:38			S73
44	BRS	7	("4191385" "4383178" "4993696" "5134640" "5301013" "5677758" "5825470").PN.	US-PGPUB; USPAT; USOCR	2005/03/28 08:46			S74
45	BRS	18	S72 and electron adj beam	US-PGPUB; USPAT; USOCR	2005/03/28 08:46			S75
46	BRS	18	S72 and electron adj beam	US-PGPUB; USPAT; USOCR	2005/03/28 08:46			S76
47	BRS	23	S59 and electron adj beam	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/28 09:17			S60
48	BRS	2	"6509957".pn.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/28 09:17			S77
49	BRS	396	stage near5 gas near5 leak\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/28 11:12			S61

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error or Definition	Error or Definition	Ref #
50	BRS	0	250/310 and stage near5 gas near5 leak\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/28 11:12				S78
51	BRS	63	electron adj beam near5 chamber and gas adj leak\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/28 11:13				S69
52	BRS	9	250/310 and electron adj beam near5 chamber and gas adj leak\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/28 11:13				S79
53	BRS	602	nakasujji-mamoru.in.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/28 11:18				S80
54	BRS	13	S80 and differential\$4 adj pump\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/28 13:13				S81
55	BRS	1	S80 and "09985322"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/28 13:15				S82

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Error	Ref #
56	BRS	0	"20020109090.did"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/03/28 13:15				S83